



#### 80071-KING BED https://youtu.be/s99s4ELGXMY

Scan QR Code for Assembly Instruction video or call customer service for video file.

IMPORTANT: PLEASE READ INSTRUCTION BEFORE STARTING THE ASSEMBLY.

"DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED"

"DO NOT OVERTIGHT ANY HARDWARE"

WARNING: SMALL PARTS AND HARDWARE NOT FOR CHILDREN UNDER 3 YEARS. ADULT ASSEMBLY REQUIRED.

TABLE OF CONTENTS		
HARDWARES LIST	PAGE 2	
PARTS LIST	PAGE 3	
PARTS' LOCATION	PAGE 4	
ASSEMBLY STEPS	PAGE 5 - 7	
ASSEMBLY COMPLETED	PAGE 8	

#### ASSEMBLY TOOLS REQUIRED

1. Screwdriver (not provide)	2. Hammer (not provide)			
<b>→</b>				
ATTENTION				

### 1. Two-Person Installation Recommendation:

We strongly recommend that two people collaborate to install the repair kit. This ensures efficiency and safety during the installation process.

### 2. Regular Screw Tightness Check:


As part of regular maintenance, it is advised to check the tightness of all screws every 6-8 weeks. This helps maintain the stability and durability of your bed frame.


HARDWARES LIST			
ITEM	DESCRIPTION	DRAWING	QTY
А	JCBC SCREW M8 x 20MM		8 PCS
В	JCBC SCREW M6 x 35MM		24 PCS
D	SPRING WASHER M6 x 12MM		24 PCS
E	FLAT WASHER M6 x 19MM		24 PCS
F	CSK C/B SCREW (M4 x 32MM)		8 PCS
G	M5 ALLEN KEY (65MM)		1 PC
Н	M4 ALLEN KEY (65MM)		1 PC
ı	SUPPORT LEG ADJUSTABLE FEET		8 PCS


<sup>\*</sup>Additional hardware included


PARTS LIST			
ITEM	DESCRIPTION	DRAWING	QTY
6	SIDE RAIL (L)		2 PCS
7	SIDE RAIL (R)		2 PCS
8	SIDE RAIL SUPPORT		4 PCS
9	SIDE RAIL LEG	0000	2 PCS
20	SLAT		2 ROLL
21	CENTER SUPPORT		4 PCS
22	SUPPORT LEG WITH HANGER BOLT		8 PCS


### **PARTS' LOCATION**














STEP 6 REMOVE THE EXISTING SIDE RAIL SET,
AND THEN REPLACE IT WITH THE NEW SIDE RAIL SET.







## **IMPORTANT**

**Discarding Original Components:** 

After successfully installing the repair kit, please discard the original components. This ensures that the bed frame operates according to the latest specifications.