80002-TWIN BED REPAIR KITS ASSEMBLY INSTRUCTION





80002-TWIN BED https://youtu.be/Fo-w3PV4bTM

Scan QR Code for Assembly Instruction video or call customer service for video file.

IMPORTANT : PLEASE READ INSTRUCTION BEFORE STARTING THE ASSEMBLY.

"DO NOT TIGHTEN SCREWS UNTIL COMPLETELY ASSEMBLED"

"DO NOT OVERTIGHT ANY HARDWARE"

WARNING : SMALL PARTS AND HARDWARE NOT FOR CHILDREN UNDER 3 YEARS. ADULT ASSEMBLY REQUIRED.

TABLE OF CONTENTS

HARDWARES LIST	PAGE 2			
PARTS LIST	PAGE 3			
PARTS' LOCATION	PAGE 4			
ASSEMBLY STEPS	PAGE 5 - 8			
ASSEMBLY COMPLETED	PAGE 9			
ASSEMBLY TOOLS REQUIRED				
1. Screwdriver (not provide)	2. Hammer (not provide)			
	7.0.1			

ATTENTION

1. Box Spring Requirement for Standard Bed Frames:

Please note that our standard bed frames are designed to be used with a box spring. Ensure that you have a suitable box spring for optimal performance.

2. Two-Person Installation Recommendation:

We strongly recommend that two people collaborate to install the repair kit. This ensures efficiency and safety during the installation process.


3. Regular Screw Tightness Check:


As part of regular maintenance, it is advised to check the tightness of all screws every 6-8 weeks. This helps maintain the stability and durability of your bed frame.

	80002-TWIN BED REPAIR KITS ASSEMBLY INSTRUCTION				
HARDWARES LIST					
ITEM	DESCRIPTION	DRAWING	QTY		
А	JCBC SCREW M8 x 20MM	()))))))))))))))))))))))))))))))))))))	4 PCS		
В	JCBC SCREW M6 x 25MM	() DIIIIIIII	8 PCS		
D	JCBC SCREW M8 x 50MM	(a)	4 PCS		
G	WOOD DOWEL M10 x 30MM		4 PCS		
Н	SPRING WASHER M6 x 13MM	I I I I I I I I I I I I I I I I I I I	8 PCS		
I	FLAT WASHER M6 x 19MM		8 PCS		
J	CSK C/B SCREW (M4 x 32MM)		8 PCS		
К	M5 ALLEN KEY (65MM)		1 PC		
L	M4 ALLEN KEY (65MM)		1 PC		
М	SPRING WASHER M8 x 14MM	\bigcirc	4 PCS		
N	FLAT WASHER M8 x 22MM	\bigcirc	4 PCS		


*Additional hardware included


		PARTS LIST	
TEM	DESCRIPTION	DRAWING	QTY
6	SIDE RAIL (L/R)	l'and the second s	2 PCS
7	SIDE RAIL (L/R)	ti at	2 PCS
8	SIDE RAIL LEG	0 0 0 0	2 PCS
9	SLAT		4 PCS






80002-TWIN BED REPAIR KITS ASSEMBLY INSTRUCTION









IMPORTANT

Discarding Original Components:

After successfully installing the repair kit, please discard the original components. This ensures that the bed frame operates according to the latest specifications.